

# POWDER METALLURGY

- The Characterization of Engineering Powders
- Production of Metallic Powders
- Conventional Pressing and Sintering
- Alternative Pressing and Sintering Techniques
- Materials and Products for PM
- Design Considerations in Powder Metallurgy

# Powder Metallurgy (PM)

Metal processing technology in which parts are produced from metallic powders

- In the usual PM production sequence, the powders are compressed (*pressed*) into the desired shape and then heated (*sintered*) to bond the particles into a hard, rigid mass
  - *Pressing* is accomplished in a press-type machine using *punch-and-die* tooling designed specifically for the part to be manufactured
  - *Sintering* is performed at a temperature below the melting point of the metal

# Why Powder Metallurgy is Important

- PM parts can be mass produced to *net shape* or *near net shape*, eliminating or reducing the need for subsequent machining
- PM process wastes very little material - about 97% of the starting powders are converted to product
- PM parts can be made with a specified level of porosity, to produce porous metal parts
  - Examples: filters, oil-impregnated bearings and gears

## More Reasons Why PM is Important

- Certain metals that are difficult to fabricate by other methods can be shaped by powder metallurgy
  - Example: Tungsten filaments for incandescent lamp bulbs are made by PM
- Certain alloy combinations and cermets made by PM cannot be produced in other ways
- PM compares favorably to most casting processes in dimensional control
- PM production methods can be automated for economical production

## Limitations and Disadvantages with PM Processing

- High tooling and equipment costs
- Metallic powders are expensive
- Problems in storing and handling metal powders
  - Examples: degradation over time, fire hazards with certain metals
- Limitations on part geometry because metal powders do not readily flow laterally in the die during pressing
- Variations in density throughout part may be a problem, especially for complex geometries

# PM Work Materials

- Largest tonnage of metals are alloys of iron, steel, and aluminum
- Other PM metals include copper, nickel, and refractory metals such as molybdenum and tungsten
- Metallic carbides such as tungsten carbide are often included within the scope of powder metallurgy




Figure 16.1 - A collection of powder metallurgy parts (courtesy of Dorst America, Inc.)

# Engineering Powders

A *powder* can be defined as a finely divided particulate solid

- Engineering powders include metals and ceramics
- Geometric features of engineering powders:
  - Particle size and distribution
  - Particle shape and internal structure
  - Surface area



# Measuring Particle Size

- Most common method uses screens of different mesh sizes
- *Mesh count* - refers to the number of openings per linear inch of screen
  - A mesh count of 200 means there are 200 openings per linear inch
  - Since the mesh is square, the count is the same in both directions, and the total number of openings per square inch is  $200^2 = 40,000$
  - Higher mesh count means smaller particle size




Figure 16.2 - Screen mesh for sorting particle sizes




Figure 16.3 - Several of the possible (ideal) particle shapes in powder metallurgy

# Interparticle Friction and Flow Characteristics

- Friction between particles affects ability of a powder to flow readily and pack tightly
- A common test of interparticle friction is the *angle of repose*, which is the angle formed by a pile of powders as they are poured from a narrow funnel




Figure 16.4 - Interparticle friction as indicated by the angle of repose of a pile of powders poured from a narrow funnel. Larger angles indicate greater interparticle friction.

# Observations

- Smaller particle sizes generally show greater friction and steeper angles
- Spherical shapes have the lowest interpartical friction
- As shape deviates from spherical, friction between particles tends to increase

# Particle Density Measures

- *True density* - density of the true volume of the material
  - The density of the material if the powders were melted into a solid mass
- *Bulk density* - density of the powders in the loose state after pouring
  - Because of pores between particles, bulk density is less than true density

## Packing Factor = Bulk Density divided by True Density

- Typical values for loose powders range between 0.5 and 0.7
- If powders of various sizes are present, smaller powders will fit into the interstices of larger ones that would otherwise be taken up by air, thus higher packing factor
- Packing can be increased by vibrating the powders, causing them to settle more tightly
- Pressure applied during compaction greatly increases packing of powders through rearrangement and deformation of particles



# Porosity

Ratio of the volume of the pores (empty spaces) in the powder to the bulk volume

- In principle, Porosity + Packing factor = 1.0
- The issue is complicated by the possible existence of closed pores in some of the particles
- If internal pore volumes are included in above porosity, then equation is exact

# Chemistry and Surface Films

- Metallic powders are classified as either
  - *Elemental* - consisting of a pure metal
  - *Pre-alloyed* - each particle is an alloy
- Possible surface films include oxides, silica, adsorbed organic materials, and moisture
  - As a general rule, these films must be removed prior to shape processing

# Production of Metallic Powders

- In general, producers of metallic powders are not the same companies as those that make PM parts
- Virtually any metal can be made into powder form
- Three principal methods by which metallic powders are commercially produced
  1. Atomization
  2. Chemical
  3. Electrolytic
- In addition, mechanical methods are occasionally used to reduce powder sizes

## Gas Atomization Method

High velocity gas stream flows through an expansion nozzle, siphoning molten metal from below and spraying it into a container

- Droplets solidify into powder form




Figure 16.5 (a) gas atomization method




Figure 16.6 - Iron powders produced by decomposition of iron pentacarbonyl; particle sizes range from about 0.25 - 3.0 microns (10 to 125  $\mu$ -in) (photo courtesy of GAF Chemicals Corporation, Advanced Materials Division)

## Conventional Press and Sinter

- After the metallic powders have been produced, the conventional PM sequence consists of three steps:
  1. *Blending* and *mixing* of the powders
  2. *Compaction* - pressing into desired part shape
  3. *Sintering* - heating to a temperature below the melting point to cause solid-state bonding of particles and strengthening of part
- In addition, secondary operations are sometimes performed to improve dimensional accuracy, increase density, and for other reasons




Figure 16.7 - Conventional powder metallurgy production sequence: (1) blending, (2) compacting, and (3) sintering; (a) shows the condition of the particles while (b) shows the operation and/or workpart during the sequence

## Blending and Mixing of Powders

- For successful results in compaction and sintering, the starting powders must be homogenized
- *Blending* - powders of the same chemistry but possibly different particle sizes are intermingled
  - Different particle sizes are often blended to reduce porosity
- *Mixing* - powders of different chemistries are combined
  - PM technology allows mixing various metals into alloys that would be difficult or impossible to produce by other means



# Compaction

Application of high pressure to the powders to form them into the required shape

- The conventional compaction method is *pressing*, in which opposing punches squeeze the powders contained in a die
- The workpart after pressing is called a *green compact*, the word green meaning not yet fully processed
- The *green strength* of the part when pressed is adequate for handling but far less than after sintering




Figure 16.9 - Pressing in PM: (1) filling die cavity with powder by automatic feeder; (2) initial and (3) final positions of upper and lower punches during pressing, and (4) ejection of part




Figure 16.11 - A 450 kN (50-ton) hydraulic press for compaction of powder metallurgy components. This press has the capability to actuate multiple levels to produce complex PM part geometries (photo courtesy Dorst America, Inc.).

# Sintering

Heat treatment to bond the metallic particles, thereby increasing strength and hardness

- Usually carried out at between 70% and 90% of the metal's melting point (absolute scale)
- Generally agreed among researchers that the primary driving force for sintering is reduction of surface energy
- Part shrinkage occurs during sintering due to pore size reduction




Figure 16.12 - Sintering on a microscopic scale: (1) particle bonding is initiated at contact points; (2) contact points grow into "necks"; (3) the pores between particles are reduced in size; and (4) grain boundaries develop between particles in place of the necked regions




Figure 16.13 - (a) Typical heat treatment cycle in sintering; and  
(b) schematic cross-section of a continuous sintering furnace

## Densification and Sizing

Secondary operations are performed to increase density, improve accuracy, or accomplish additional shaping of the sintered part

- *Repressing* - pressing the sintered part in a closed die to increase density and improve properties
- *Sizing* - pressing a sintered part to improve dimensional accuracy
- *Coining* - pressworking operation on a sintered part to press details into its surface
- *Machining* - creates geometric features that cannot be achieved by pressing, such as threads, side holes, and other details

# Impregnation and Infiltration

- Porosity is a unique and inherent characteristic of PM technology
- It can be exploited to create special products by filling the available pore space with oils, polymers, or metals
- Two categories:
  1. Impregnation
  2. Infiltration



# Impregnation

The term used when oil or other fluid is permeated into the pores of a sintered PM part

- Common products are oil-impregnated bearings, gears, and similar components
- An alternative application is when parts are impregnated with polymer resins that seep into the pore spaces in liquid form and then solidify to create a pressure tight part

# Infiltration

An operation in which the pores of the PM part are filled with a molten metal

- The melting point of the filler metal must be below that of the PM part
- Involves heating the filler metal in contact with the sintered component so capillary action draws the filler into the pores
- The resulting structure is relatively nonporous, and the infiltrated part has a more uniform density, as well as improved toughness and strength

# Alternative Pressing and Sintering Techniques

- The conventional press and sinter sequence is the most widely used shaping technology in powder metallurgy
- Additional methods for processing PM parts include:
  - Isostatic pressing
  - Hot pressing - combined pressing and sintering

# Materials and Products for PM

- Raw materials for PM are more expensive than for other metalworking because of the additional energy required to reduce the metal to powder form
- Accordingly, PM is competitive only in a certain range of applications
- What are the materials and products that seem most suited to powder metallurgy?

# PM Materials – Elemental Powders

A pure metal in particulate form

- Used in applications where high purity is important
- Common elemental powders:
  - Iron
  - Aluminum
  - Copper
- Elemental powders are also mixed with other metal powders to produce special alloys that are difficult to formulate by conventional methods
  - Example: tool steels

# PM Materials – Pre-Alloyed Powders

Each particle is an alloy comprised of the desired chemical composition

- Used for alloys that cannot be formulated by mixing elemental powders
- Common pre-alloyed powders:
  - Stainless steels
  - Certain copper alloys
  - High speed steel

## PM Products

- Gears, bearings, sprockets, fasteners, electrical contacts, cutting tools, and various machinery parts
- Advantage of PM: parts can be made to near net shape or net shape
  - They require little or no additional shaping after PM processing
- When produced in large quantities, gears and bearings are ideal for PM because:
  - The geometry is defined in two dimensions
  - There is a need for porosity in the part to serve as a reservoir for lubricant

# PM Parts Classification System

- The Metal Powder Industries Federation (MPIF) defines four classes of powder metallurgy part designs, by level of difficulty in conventional pressing
- Useful because it indicates some of the limitations on shape that can be achieved with conventional PM processing






Figure 16.16 - Four classes of PM parts (side view shown; cross-section is circular): (a) Class I - simple thin shapes, pressed from one direction; (b) Class II - simple but thicker shapes require pressing from two directions; (c) Class III - two levels of thickness, pressed from two directions; and (d) Class IV - multiple levels of thickness, pressed from two directions, with separate controls for each level

## Design Guidelines for PM Parts - I

- Economics usually require large quantities to justify cost of equipment and special tooling
  - Minimum quantities of 10,000 units are suggested
- PM is unique in its capability to fabricate parts with a controlled level of porosity
  - Porosities up to 50% are possible
- PM can be used to make parts out of unusual metals and alloys - materials that would be difficult if not impossible to produce by other means

## Design Guidelines for PM Parts - II

- The part geometry must permit ejection from die after pressing
  - This generally means that part must have vertical or near-vertical sides, although steps are allowed
  - Design features such as undercuts and holes on the part sides must be avoided
  - Vertical undercuts and holes are permissible because they do not interfere with ejection
  - Vertical holes can be of cross-sectional shapes other than round without significant difficulty




Figure 16.17 - Part features to be avoided in PM: side holes and (b) side undercuts since part ejection is impossible

## Design Guidelines for PM Parts - III

- Screw threads cannot be fabricated by PM; if required, they must be machined into the part
- Chamfers and corner radii are possible by PM pressing, but problems arise in punch rigidity when angles are too acute
- Wall thickness should be a minimum of 1.5 mm (0.060 in) between holes or a hole and outside wall
- Minimum recommended hole diameter is 1.5 mm (0.060 in)




Figure 16.19 - Chamfers and corner radii are accomplished but certain rules should be observed: (a) avoid acute angles; (b) larger angles preferred for punch rigidity; (c) inside radius is desirable; (d) avoid full outside corner radius because punch is fragile at edge; (e) problem solved by combining radius and chamfer