



## **Material Removal Processes**

- A family of shaping operations, the common feature of which is removal of material from a starting workpart so the remaining part has the desired shape
- Categories:
  - Machining material removal by a sharp cutting tool, e.g., turning, milling, drilling
  - Abrasive processes material removal by hard, abrasive particles, e.g., grinding
  - Nontraditional processes various energy forms other than sharp cutting tool to remove material



Figure 21.2 - (a) A cross-sectional view of the machining process, (b) tool with negative rake angle; compare with positive rake angle in (a)

# Why Machining is Important

- Variety of work materials can be machined
  - Most frequently applied to metals
- Variety of part shapes and special geometry features possible, such as:
  - Screw threads
  - Accurate round holes
  - Very straight edges and surfaces
- Good dimensional accuracy and surface finish



# <section-header><section-header><section-header><list-item><list-item><list-item>





























©2002 John Wiley & Sons, Inc. M. P. Groover,











# Continuous with BUE

- Ductile materials
- Low-to-medium cutting speeds
- Tool-chip friction causes portions of chip to adhere to rake face
- BUE formation is cyclical; it forms, then breaks off

Figure 21.9 - Four types of chip formation in metal cutting: (c) continuous with built-up edge





## Forces Acting on Chip

- Friction force F and Normal force to friction N
- Shear force  $F_s$  and Normal force to shear  $F_n$





















































# Work Holding for Drill Presses

- · Workpart can be clamped in a vise, fixture, or jig
  - Vise general purpose workholder with two jaws
  - Fixture workholding device that is usually custom-designed for the particular workpart
  - Drill jig similar to fixture but also provides a means of guiding the tool during drilling





















## Surface Contouring

Ball-nose cutter is fed back and forth across the work along a curvilinear path at close intervals to create a three dimensional surface form

Figure 22.20 (f) surface contouring









# **Machining Centers**

Highly automated machine tool capable of performing multiple machining operations under CNC control in one setup with minimal human attention

- Typical operations are milling and drilling
- Three, four, or five axes
- Other features:
  - Automatic tool-changing
  - Pallet shuttles
  - Automatic workpart positioning

Dept. of Naval Architecture and Marine Engineering























# High Speed Machining (HSM)

# Cutting at speeds significantly higher than those used in conventional machining operations

- A persistent trend throughout history of machining is higher and higher cutting speeds
- At present there is a renewed interest in HSM due to potential for faster production rates, shorter lead times, and reduced costs

Dept. of Naval Architecture and Marine Engineering

					YPAL	AC
	High	n Spee	d Mach	ining		
Compariso	on of cor	ventiona	l vs. high	speed m	achining	
		Indexable tools (face mills)				
Work ma	Work material		Conventional speed		High speed	
		m/min	ft/min	m/min	ft/min	
Aluminur	n	600+	2000+	3600+	12,000+	
Cast iron	Cast iron, soft		1200	1200	4000	
Cast iron	Cast iron, ductile		800	900	3000	
Steel, alloy		210	700	360	1200	
Source:	Kenname	tal Inc.				

# ECONOMIC AND PRODUCT DESIGN CONSIDERATIONS IN MACHINING

- Machinability
- Tolerances and Surface Finish
- Selection of Cutting Conditions
- Product Design Considerations in Machining

©2002 John Wiley & Sons Inc. M. P. Grooverngineering



# Machinability Criteria in Production

- Tool life how long the tool lasts for the given work material
- Forces and power greater forces and power mean lower machinability
- *Surface finish* better finish means better machinability
- Ease of chip disposal easier chip disposal means better machinability

©2002 John Wiley & Sons Inc. M. P. GrooveEngineering





©2002 John Wiley & Sons Inc. M. P. Grooverngineering





# Tolerances and Surface Finish in Machining

- Tolerances
  - Machining provides high accuracy relative to most other shape-making processes
  - Closer tolerances usually mean higher costs
- Surface roughness in machining is determined by:
  - Geometric factors of the operation
  - Work material factors
  - Vibration and machine tool factors

©2002 John Wiley & Sons Inc. M. P. GrooveEngineering



















# How To Avoid Chatter (Vibration)

- · Add stiffness and/or damping to setup
- Operate at speeds that avoid cyclical forces with frequencies close to natural frequency of machine tool system
- Reduce feeds and depths to reduce forces
- Change cutter design to reduce forces
- Use a cutting fluid

©2002 John Wiley & Sons Inc. M. P. GrooveEngineering



# Selecting Depth of Cut

- Depth of cut is often predetermined by workpiece geometry and operation sequence
  - In roughing, depth is made as large as possible to maximize material removal rate, subject to limitations of horsepower, machine tool and setup rigidity, and strength of cutting tool
  - In finishing, depth is set to achieve final part dimensions

©2002 John Wiley & Sons Inc. e M. P. Grooverngineering



# **Optimizing Cutting Speed**

- Select speed to achieve a balance between high metal removal rate and suitably long tool life
- Mathematical formulas are available to determine optimal speed
- Two alternative objectives in these formulas:
  - 1. Maximum production rate
  - 2. Minimum unit cost

©2002 John Wiley & Sons Inc. M. P. GrooveEngineering







53







![](_page_54_Picture_2.jpeg)

# <section-header><list-item><list-item><list-item><list-item>

![](_page_55_Figure_3.jpeg)

![](_page_56_Figure_1.jpeg)

![](_page_56_Figure_2.jpeg)

![](_page_57_Figure_1.jpeg)

![](_page_57_Figure_2.jpeg)

![](_page_58_Figure_1.jpeg)

![](_page_58_Figure_2.jpeg)

![](_page_59_Figure_1.jpeg)

![](_page_59_Figure_2.jpeg)