#### GIM2042 Manufacturing Processes, Gr. 2, T.302

Lecturer; Assoc. Prof.Dr.Yüksel PALACI Office ; T403 E-mail ; ypalaci@yildiz.edu.tr

- Book; John Wiley & Sons, Inc. M. P. Groover, "Fundamentals of Modern Manufacturing"
- Chapters:1,10,11,16,18-22,24,30-34
- http://www.bologna.yildiz.edu.tr/index.php?r=course/v iew&id=1171&aid=35


Dept. of Naval Architecture and Marine Engineering

# <section-header> POWDER METALLURGY POWDER METALLURGY The Characterization of Engineering Powders Production of Metallic Powders Conventional Pressing and Sintering Alternative Pressing and Sintering Techniques Materials and Products for PM Design Considerations in Powder Metallurgy

# Powder Metallurgy (PM)

Metal processing technology in which parts are produced from metallic powders

- In the usual PM production sequence, the powders are compressed (*pressed*) into the desired shape and then heated (*sintered*) to bond the particles into a hard, rigid mass
  - Pressing is accomplished in a press-type machine using *punch-and-die* tooling designed specifically for the part to be manufactured
  - Sintering is performed at a temperature below the melting point of the metal



# More Reasons Why PM is Important

- Certain metals that are difficult to fabricate by other methods can be shaped by powder metallurgy
  - Example: Tungsten filaments for incandescent lamp bulbs are made by PM
- Certain alloy combinations and cermets made by PM cannot be produced in other ways
- PM compares favorably to most casting processes in dimensional control
- PM production methods can be automated for economical production

Dept. of Naval Architecture and Marine Engineering

YPALACI

# Limitations and Disadvantages with PM Processing


- High tooling and equipment costs
- Metallic powders are expensive
- Problems in storing and handling metal powders
  - Examples: degradation over time, fire hazards with certain metals
- Limitations on part geometry because metal powders do not readily flow laterally in the die during pressing
- Variations in density throughout part may be a problem, especially for complex geometries

# **PM Work Materials**

YPALACI


- Largest tonnage of metals are alloys of iron, steel, and aluminum
- Other PM metals include copper, nickel, and refractory metals such as molybdenum and tungsten
- Metallic carbides such as tungsten carbide are often included within the scope of powder metallurgy


Dept. of Naval Architecture and Marine Engineering





# **Engineering Powders**


- A *powder* can be defined as a finely divided particulate solid
- Engineering powders include metals and ceramics
- Geometric features of engineering powders:
  - Particle size and distribution
  - Particle shape and internal structure
  - Surface area













# **Observations**

- Smaller particle sizes generally show greater friction and steeper angles
- Spherical shapes have the lowest interpartical friction
- As shape deviates from spherical, friction between particles tends to increase




# Packing Factor = Bulk Density divided by True Density

- Typical values for loose powders range between 0.5 and 0.7
- If powders of various sizes are present, smaller powders will fit into the interstices of larger ones that would otherwise be taken up by air, thus higher packing factor
- Packing can be increased by vibrating the powders, causing them to settle more tightly
- Pressure applied during compaction greatly increases packing of powders through rearrangement and deformation of particles



# **Chemistry and Surface Films**


- Metallic powders are classified as either
  - Elemental consisting of a pure metal
  - Pre-alloyed each particle is an alloy
- Possible surface films include oxides, silica, adsorbed organic materials, and moisture
  - As a general rule, these films must be removed prior to shape processing




# **Gas Atomization Method**

High velocity gas stream flows through an expansion nozzle, siphoning molten metal from below and spraying it into a container


Droplets solidify into powder form







# **Conventional Press and Sinter**

- After the metallic powders have been produced, the conventional PM sequence consists of three steps:
  - 1. Blending and mixing of the powders
  - 2. Compaction pressing into desired part shape
  - Sintering heating to a temperature below the melting point to cause solid-state bonding of particles and strengthening of part
- In addition, secondary operations are sometimes performed to improve dimensional accuracy, increase density, and for other reasons









Dept. of Naval Architecture and Marine Engineering




Figure 16.11 - A 450 kN (50-ton) hydraulic press for compaction of powder metallurgy components. This press has the capability to actuate multiple levels to produce complex PM part geometries (photo courtesy Dorst America, Inc.).

YPALACI



×

# Distribution Distribution<

Dept. of Naval Architecture and Marine Engineering






Figure 16.12 - Sintering on a microscopic scale: (1) particle bonding is initiated at contact points; (2) contact points grow into "necks"; (3) the pores between particles are reduced in size; and (4) grain boundaries develop between particles in place of the necked regions











# Infiltration

An operation in which the pores of the PM part are filled with a molten metal

- The melting point of the filler metal must be below that of the PM part
- Involves heating the filler metal in contact with the sintered component so capillary action draws the filler into the pores
- The resulting structure is relatively nonporous, and the infiltrated part has a more uniform density, as well as improved toughness and strength

Dept. of Naval Architecture and Marine Engineering

YPALACI


# Alternative Pressing and Sintering Techniques

- The conventional press and sinter sequence is the most widely used shaping technology in powder metallurgy
- Additional methods for processing PM parts include:
  - Isostatic pressing
  - Hot pressing combined pressing and sintering



# Materials and Products for PM

- Raw materials for PM are more expensive than for other metalworking because of the additional energy required to reduce the metal to powder form
- Accordingly, PM is competitive only in a certain range of applications
- What are the materials and products that seem most suited to powder metallurgy?



# PM Materials – Pre-Alloyed Powders

Each particle is an alloy comprised of the desired chemical composition

- Used for alloys that cannot be formulated by mixing elemental powders
- Common pre-alloyed powders:
  - Stainless steels
  - Certain copper alloys
  - High speed steel

Dept. of Naval Architecture and Marine Engineering

#### **PM Products**

- Gears, bearings, sprockets, fasteners, electrical contacts, cutting tools, and various machinery parts
- Advantage of PM: parts can be made to near net shape or net shape
  - They require little or no additional shaping after PM processing
- When produced in large quantities, gears and bearings are ideal for PM because:
  - The geometry is defined in two dimensions
  - There is a need for porosity in the part to serve as a reservoir for lubricant

# **PM Parts Classification System**

- The Metal Powder Industries Federation (MPIF) defines four classes of powder metallurgy part designs, by level of difficulty in conventional pressing
- Useful because it indicates some of the limitations on shape that can be achieved with conventional PM processing

#### Dept. of Naval Architecture and Marine Engineering





Figure 16.16 - Four classes of PM parts (side view shown; cross-section is circular): (a) Class I - simple thin shapes, pressed from one direction; (b) Class II - simple but thicker shapes require pressing from two directions; (c) Class III - two levels of thickness, pressed from two directions; and (d) Class IV - multiple levels of thickness, pressed from two directions, with separate controls for each level




# Design Guidelines for PM Parts - I

- Economics usually require large quantities to justify cost of equipment and special tooling
  - Minimum quantities of 10,000 units are suggested
- PM is unique in its capability to fabricate parts with a controlled level of porosity
  - Porosities up to 50% are possible
- PM can be used to make parts out of unusual metals and alloys - materials that would be difficult if not impossible to produce by other means










Figure 16.19 - Chamfers and corner radii are accomplished but certain rules should be observed: (a) avoid acute angles; (b) larger angles preferred for punch rigidity; (c) inside radius is desirable; (d) avoid full outside corner radius because punch is fragile at edge; (e) problem solved by combining radius and chamfer