

#### GIM2042 Manufacturing Processes, Gr. 2, T.301

Lecturer; Assoc. Prof.Dr.Yüksel PALACI

Office ; T403

E-mail ; ypalaci@yildiz.edu.tr

- Book; John Wiley & Sons, Inc. M. P. Groover, "Fundamentals of Modern Manufacturing"
- Chapters:1,10,11,16,18-22,24,30-34
- http://www.bologna.yildiz.edu.tr/index.php?r=course/v iew&id=1171&aid=35

Dept. of Naval Architecture and Marine Engineering



**YPALACI** 

# BULK DEFORMATION PROCESSES IN METALWORKING

- Rolling
- Other Deformation Processes Related to Rolling
- Forging
- · Other Deformation Processes Related to Forging
- Extrusion
- Wire and Bar Drawing



#### **Bulk Deformation**

Metal forming operations which cause significant shape change by deformation in metal parts whose initial form is bulk rather than sheet

- Starting forms: cylindrical bars and billets, rectangular billets and slabs, and similar shapes
- These processes work by stressing metal sufficiently to cause plastic flow into desired shape
- Performed as cold, warm, and hot working operations

Dept. of Naval Architecture and Marine Engineering



**YPALACI** 

# Importance of Bulk Deformation

- In hot working, significant shape change can be accomplished
- In cold working, strength can be increased during shape change
- Little or no waste some operations are near net shape or net shape processes
  - The parts require little or no subsequent machining

©2002 John Wiley & Sons Inc. M. P. Groover Bept. of Naval Architecture and Marine Engineering



#### Four Basic Bulk Deformation Processes

- Rolling slab or plate is squeezed between opposing rolls
- 2. Forging work is squeezed and shaped between between opposing dies
- 3. Extrusion work is squeezed through a die opening, thereby taking the shape of the opening
- 4. Wire and bar drawing diameter of wire or bar is reduced by pulling it through a die opening

Dept. of Naval Architecture and Marine Engineering

# Rolling Deformation process in which work thickness is reduced by compressive forces exerted by two opposing rolls Direction of work flow Work Figure 19.1 - The rolling process (specifically, flat rolling)



#### The Rolls

The rotating rolls perform two main functions:

- Pull the work into the gap between them by friction between workpart and rolls
- Simultaneously squeeze the work to reduce cross section


Dept. of Naval Architecture and Marine Engineering




VPAT ACT

# Types of Rolling

- By geometry of work:
  - Flat rolling used to reduce thickness of a rectangular cross-section
  - Shape rolling a square cross-section is formed into a shape such as an I-beam
- · By temperature of work:
  - Hot Rolling most common due to the large amount of deformation required
  - Cold rolling produces finished sheet and plate stock







# Flat Rolling – Terminology

*Draft* = amount of thickness reduction

$$d = t_O - t_f$$

where d = draft;  $t_o = \text{starting thickness}$ ; and  $t_f = \text{final thickness}$ 

Dept. of Naval Architecture and Marine Engineering



#### **YPALACI**

# Flat Rolling - Terminology

Reduction = draft expressed as a fraction of starting stock thickness:

$$r = \frac{d}{t_o}$$

where r = reduction




# **Shape Rolling**

Work is deformed into a contoured cross-section rather than flat (rectangular)

- Accomplished by passing work through rolls that have the reverse of desired shape
- · Products include:
  - Construction shapes such as I-beams, L-beams, and U-channels
  - Rails for railroad tracks
  - Round and square bars and rods

Dept. of Naval Architecture and Marine Engineering



**YPALACI** 


Figure 19.5 - A
rolling mill for hot
flat rolling; the
steel plate is
seen as the
glowing strip
extending
diagonally from
the lower left
corner
(photo courtesy
of Bethlehem
Steel Company)





# **Rolling Mills**


- Equipment is massive and expensive
- Rolling mill configurations:
  - Two-high two opposing large diameter rolls
  - Three-high work passes through both directions
  - Four-high backing rolls support smaller work rolls
  - Cluster mill multiple backing rolls on smaller rolls
  - Tandem rolling mill sequence of two-high mills


Dept. of Naval Architecture and Marine Engineering














## **Thread Rolling**

Bulk deformation process used to form threads on cylindrical parts by rolling them between two dies

- Most important commercial process for mass producing bolts and screws
- Performed by cold working in thread rolling machines
- Advantages over thread cutting (machining):
  - Higher production rates
  - Better material utilization
  - Stronger threads due to work hardening
  - Better fatigue resistance due to compressive stresses introduced by rolling






#### Ring Rolling

Deformation process in which a thick-walled ring of smaller diameter is rolled into a thin-walled ring of larger diameter

- As thick-walled ring is compressed, deformed metal elongates, causing diameter of ring to be enlarged
- Hot working process for large rings and cold working process for smaller rings
- Applications: ball and roller bearing races, steel tires for railroad wheels, and rings for pipes, pressure vessels, and rotating machinery
- Advantages: material savings, ideal grain orientation, strengthening through cold working





## **Forging**

Deformation process in which work is compressed between two dies

- Oldest of the metal forming operations, dating from about 5000 B C
- Components: engine crankshafts, connecting rods, gears, aircraft structural components, jet engine turbine parts
- In addition, basic metals industries use forging to establish basic form of large components that are subsequently machined to final shape and size

Dept. of Naval Architecture and Marine Engineering



**YPALACI** 


### Classification of Forging Operations


- Cold vs. hot forging:
  - Hot or warm forging most common, due to the significant deformation and the need to reduce strength and increase ductility of work metal
  - Cold forging advantage is increased strength that results from strain hardening
- · Impact vs. press forging:
  - Forge hammer applies an impact load
  - Forge press applies gradual pressure




# Types of Forging Dies

- Open-die forging work is compressed between two flat dies, allowing metal to flow laterally without constraint
- Impression-die forging die surfaces contain a cavity or impression that is imparted to workpart, thus constraining metal flow - flash is created
- Flashless forging workpart is completely constrained in die and no excess flash is produced









# **Open-Die Forging**

Compression of workpart with cylindrical cross-section between two flat dies

- Similar to compression test
- Deformation operation reduces height and increases diameter of work
- Common names include upsetting or upset forging

Dept. of Naval Architecture and Marine Engineering



**YPALACI** 


#### Open-Die Forging with No Friction

If no friction occurs between work and die surfaces, then homogeneous deformation occurs, so that radial flow is uniform throughout workpart height and true strain is given by:

$$\varepsilon = \ln \frac{h_0}{h}$$

where  $h_o$ = starting height; and h = height at some point during compression

• At  $h = \text{final value } h_{f_t} \text{ true strain is maximum value}$ 






#### YPAT ACT

# Open-Die Forging with Friction

- Friction between work and die surfaces constrains lateral flow of work, resulting in barreling effect
- In hot open-die forging, effect is even more pronounced due to heat transfer at and near die surfaces, which cools the metal and increases its resistance to deformation






# Impression-Die Forging

Compression of workpart by dies with inverse of desired part shape

- Flash is formed by metal that flows beyond die cavity into small gap between die plates
- Flash must be later trimmed from part, but it serves an important function during compression:
  - As flash forms, friction resists continued metal flow into gap, constraining material to fill die cavity
  - In hot forging, metal flow is further restricted by cooling against die plates





# Impression-Die Forging Practice

- Several forming steps often required, with separate die cavities for each step
  - Beginning steps redistribute metal for more uniform deformation and desired metallurgical structure in subsequent steps
  - Final steps bring the part to its final geometry
  - Impression-die forging is often performed manually by skilled operator under adverse conditions



# Impression-Die Forging Advantages and Limitations

- Advantages compared to machining from solid stock:
  - Higher production rates
  - Conservation of metal (less waste)
  - Greater strength
  - Favorable grain orientation in the metal.
- Limitations:
  - Not capable of close tolerances
  - Machining often required to achieve accuracies and features needed, such as holes, threads, and mating surfaces that fit with other components

Dept. of Naval Architecture and Marine Engineering




YPALAC:

#### Flashless Forging

Compression of work in punch and die tooling whose cavity does allow for flash


- Starting workpart volume must equal die cavity volume within very close tolerance
- Process control more demanding than impression-die forging
- Best suited to part geometries that are simple and symmetrical
- Often classified as a precision forging process






# Forging Hammers (Drop Hammers)

- Apply an impact load against workpart two types:
  - Gravity drop hammers impact energy from falling weight of a heavy ram
  - Power drop hammers accelerate the ram by pressurized air or steam
- Disadvantage: impact energy transmitted through anvil into floor of building
- Most commonly used for impression-die forging







#### **Forging Presses**

- Apply gradual pressure to accomplish compression operation types:
  - Mechanical presses converts rotation of drive motor into linear motion of ram
  - Hydraulic presses hydraulic piston actuates ram
  - Screw presses screw mechanism drives ram

Dept. of Naval Architecture and Marine Engineering





YPALACI

#### **Upsetting and Heading**

Forging process used to form heads on nails, bolts, and similar hardware products

- More parts produced by upsetting than any other forging operation
- Performed cold, warm, or hot on machines called headers or formers
- Wire or bar stock is fed into machine, end is headed, then piece is cut to length
- For bolts and screws, thread rolling is then used to form threads







#### YPALAC:

## **Swaging**

Accomplished by rotating dies that hammer a workpiece radially inward to taper it as the piece is fed into the dies

- Used to reduce diameter of tube or solid rod stock
- Mandrel sometimes required to control shape and size of internal diameter of tubular parts

Dept. of Naval Architecture and Marine Engineering




Figure 19.25 - Swaging process to reduce solid rod stock; the dies rotate as they hammer the work. In radial forging, the workpiece rotates while the dies remain in a fixed orientation as they hammer the work.




YPALAC:

# **Trimming**

Cutting operation to remove flash from workpart in impression-die forging

- Usually done while work is still hot, so a separate trimming press is included at the forging station
- Trimming can also be done by alternative methods, such as grinding or sawing






#### Extrusion

Compression forming process in which the work metal is forced to flow through a die opening to produce a desired cross-sectional shape


- Process is similar to squeezing toothpaste out of a toothpaste tube
- In general, extrusion is used to produce long parts of uniform cross-sections
- Two basic types of extrusion:
  - Direct extrusion
  - Indirect extrusion






#### Comments on Direct Extrusion

- Also called forward extrusion
- As ram approaches die opening, a small portion of billet remains that cannot be forced through die opening
- This extra portion, called the butt, must be separated from extruded product by cutting it just beyond the die exit
- Starting billet cross section usually round, but final shape is determined by die opening







## Comments on Indirect Extrusion

- Also called backward extrusion and reverse extrusion
- Limitations of indirect extrusion are imposed by the lower rigidity of hollow ram and difficulty in supporting extruded product as it exits die



## General Advantages of Extrusion

- Variety of shapes possible, especially in hot extrusion
  - Limitation: part cross-section must be uniform throughout length
- Grain structure and strength enhanced in cold and warm extrusion
- Close tolerances possible, especially in cold extrusion
- In some operations, little or no waste of material

Dept. of Naval Architecture and Marine Engineering



YPALAC:

#### Hot vs. Cold Extrusion

- Hot extrusion prior heating of billet to above its recrystallization temperature
  - This reduces strength and increases ductility of the metal, permitting more size reductions and more complex shapes
- Cold extrusion generally used to produce discrete parts
  - The term *impact extrusion* is used to indicate high speed cold extrusion



YPALAC:


#### **Extrusion Ratio**

Also called the reduction ratio, it is defined as

$$r_X = \frac{A_O}{A_f}$$

where  $r_x$  = extrusion ratio;  $A_o$  = cross-sectional area of the starting billet; and  $A_f$  = final cross-sectional area of the extruded section

Applies to both direct and indirect extrusion





## Comments on Die Angle

- Low die angle surface area is large, leading to increased friction at die-billet interface
  - Higher friction results in larger ram force
- Large die angle more turbulence in metal flow during reduction
  - Turbulence increases ram force required
- Optimum angle depends on work material, billet temperature, and lubrication

Dept. of Naval Architecture and Marine Engineering



**YPALACI** 

# Comments on Orifice Shape of Extrusion Die

- Simplest cross section shape = circular die orifice
- Shape of die orifice affects ram pressure
- As cross-section becomes more complex, higher pressure and greater force are required






Figure 19.37 - A complex extruded cross-section for a heat sink (photo courtesy of Aluminum Company of America)

Dept. of Naval Architecture and Marine Engineering



#### YPAT ACT

#### **Extrusion Presses**


- · Either horizontal or vertical
  - Horizontal more common
- Extrusion presses usually hydraulically driven, which is especially suited to semi-continuous direct extrusion of long sections
- Mechanical drives often used for cold extrusion of individual parts



## Wire and Bar Drawing

Cross-section of a bar, rod, or wire is reduced by pulling it through a die opening

- Similar to extrusion except work is *pulled* through die in drawing (it is *pushed* through in extrusion)
- Although drawing applies tensile stress, compression also plays a significant role since metal is squeezed as it passes through die opening





#### Area Reduction in Drawing

Change in size of work is usually given by area reduction:

$$r = \frac{A_0 - A_f}{A_0}$$

where r = area reduction in drawing;  $A_o$  = original area of work; and  $A_r$  = final work

Dept. of Naval Architecture and Marine Engineering



**YPALACI** 

# Wire Drawing vs. Bar Drawing

- Difference between bar drawing and wire drawing is stock size
  - Bar drawing large diameter bar and rod stock
  - Wire drawing small diameter stock wire sizes down to 0.03 mm (0.001 in.) are possible
- Although the mechanics are the same, the methods, equipment, and even terminology are different



# **Drawing Practice and Products**

- · Drawing practice:
  - Usually performed as cold working
  - Most frequently used for round cross-sections
- Products:
  - Wire: electrical wire; wire stock for fences, coat hangers, and shopping carts
  - Rod stock for nails, screws, rivets, and springs
  - Bar stock: metal bars for machining, forging, and other processes


Dept. of Naval Architecture and Marine Engineering



**YPALACI** 

## **Bar Drawing**


- Accomplished as a single-draft operation the stock is pulled through one die opening
- Beginning stock has large diameter and is a straight cylinder
- This necessitates a batch type operation





# Wire Drawing


- Continuous drawing machines consisting of multiple draw dies (typically 4 to 12) separated by accumulating drums
  - Each drum (capstan) provides proper force to draw wire stock through upstream die
  - Each die provides a small reduction, so desired total reduction is achieved by the series
  - Annealing sometimes required between dies





#### Features of a Draw Die

- Entry region funnels lubricant into the die to prevent scoring of work and die
- Approach cone-shaped region where drawing occurs
- · Bearing surface determines final stock size
- Back relief exit zone provided with a back relief angle (half-angle) of about 30°
- Die materials: tool steels or cemented carbides



# Preparation of the Work for Wire or Bar Drawing - Annealing – to increase ductility of stock - Cleaning - to prevent damage to work surface and draw die - Pointing – to reduce diameter of starting end to allow insertion through draw die Dept. of Naval Architecture and Marine Engineering